


## WFH Desk 4



No Tools Required  
Assembly time 5 minutes



Locate brace into cut-outs  
Push down "click".  
Pull ring & lift to remove



Locate desktop in cut-outs  
Slide forward "click"  
Pull ring & slide backwards to remove

